	Туре	L #	Hits	Search Text	DBs	Time	Stamp	Comments
1	BRS	L6		(crankshaft and cylinder and bolts and bearing with collar).clm.		12:34	06/18	
2	BRS	L7	106	(crankshaft and cylinder and bolts and bearing).clm.	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B	12:34	06/18	